


Water Meter Installation Diagram



The water meter must be mounted horizontally at least 15 inches off the floor and no higher than 60 inches from the floor. It must be located in a place that will be accessible for inspection and maintenance.

PLEASE NOTE:

Be sure the plumber seals the holes that penetrate your basement walls where the service lines enter. This is to avoid water seepage entering your basement, THIS IS FOR YOUR PROTECTION!